

ATTENTION MACINTOSH USERS

The table below illustrates the behavior of the Adtron software and Formatter with specific versions of MacOS. Certain anomalies in the different versions of MacOS produce varied results.

Auto Mounting

In MacOS 8.5, the system may not automatically "mount" the PC Card when inserted after booting. To fix this problem, either:

- A) Go into File Exchange and click the "Mount Now" button. Subsequent mounting will be automatic. This will have to be performed upon every restart.

OR

- B) Insert the card before booting the system.

This problem can be solved by upgrading File Exchange or upgrading to MacOS 8.6.

Multiple LUNs

MacOS 8.5 and below only recognizes the first Logical Unit Number (LUN). This only affects users of the Adtron SDDS, which has two PC Card slots. Only the top slot of the SDDS will be recognized.

- NOTE -

Drag the PC Card icon to the Trash before removing the PC Card. Do NOT simply eject the card, as this may cause the system to "hang". Re-insert the PC Card and then drag it to the trash.

MacOS Version	Exchange Version	Auto Mount	Multiple LUNs
8.6	3.01	Yes	Yes
8.5	3.0	No	No
8.1	2.11	Yes	No
7.5.3	2.05	Yes	No

MacOS Version: The version of the Macintosh Operating System, such as MacOS 8.5.

Exchange Version: The version of File Exchange (OS 8.5 or above) or PC Exchange (OS 8.1 and below). Not every version is listed.

Auto Mount: Whether the system automatically "mounts" an inserted PC Card on the desktop.

Multiple LUNs: Whether the system recognizes multiple Logical Unit Numbers (LUNs). Each PC Card slot is a LUN and some systems only recognize the first LUN.